



Series DLK

hohner

Elektrotechnik Werne

Certifications

Does not require a barrier for use in hazardous areas, it is **Flameproof**, making the barrier redundant. IP 66/X7

IP 00/X/

Ex d IIC

ATEX [Certificate]

IECEx [Certificate]

Mounting Instructions

Hook up the encoder with the connections as described. Make sure power supply meets specifications. Attach encoder to mounting bracket as shown. Attach shaft using a flexible coupling.



Dimensions

